


2,3 GHz TRV LO switch



TCXOs are working continuously

2,3 GHz TRV LO switch

TITLE: tcxo2ghzblock

Document Number:

REV:

Date: 01.01.2008 23:45:10

Sheet: 1/1